SPEC SHEET + MEASUREMENTS

Wink® Women's Premiere Flex™ Full-Zip Scrub Jacket.

WW4088

Product photo



- 78/20/2 poly/rayon/spandex
- Zippered front closure
- Shoulder badge loop
- Rib knit cuffs
- Top-loading front pockets with interior pocket
- Side vents
- Wink® heat transfer logo at left pocket
- Modern fit

CARE INSTRUCTIONS

Machine Wash Cold With Like Colors. Gentle Cycle. Use Only Non-Chlorine Bleach When Needed. Tumble Dry Low. Remove Promptly From Dryer. Cool Iron When Needed.

Sketches



front



back

SPEC SHEET + MEASUREMENTS

Wink® Women's Premiere Flex™ Full-Zip Scrub Jacket.

WW4088

PRODUCT MEASUREMENTS

	2XS	XS	S	M	L	XL	2XL	3XL	4XL	5XL
Body Length at Back	26 1/2	27	27 1/2	28 1/4	29	29 3/4	30 1/2	31 1/4	32	32 3/4
Bust	34	37	40	43	46	50	54	58	62	66
Set in Sleeve Length	24	24 1/4	24 1/2	24 5/8	24 3/4	24 7/8	25	25 1/8	25 1/4	25 3/8
Size	0	2	4-6	8-10	12-14	16-18	20-22	24-26	28-30	32-34

Body Length at Back: Measured from high point shoulder to finished hem at back.

Bust: Measured across the chest one inch below armhole when laid flat.

Set in Sleeve Length: Measure from Center Back neck to shoulder point to sleeve hem.

SIZE CHARTS


	2XS	XS	S	M	L	XL	2XL	3XL	4XL	5XL
Bust	30-31	32-33	34-35	36-38	39-42	43-46	47-50	51-54	55-58	59-62
Size	0	2-4	6-8	10-12	14-16	18-20	22-24	26-28	30-32	34-36

SPEC SHEET + MEASUREMENTS

Wink® Women's Premiere Flex™ Full-Zip Scrub Jacket.

WW4088

HOW TO MEASURE



BUST

Measure under the arm and around the fullest part of the bust with arms down, keeping tape horizontal.

COLORS

Black	Ceil Blue	Navy	Pewter	Royal	Teal Blue	White	Wine
PMS PROCESS BLACK C	PMS 659C	PMS 654C	PMS 432C	PMS 2145C	PMS 320C		PMS 222C