SPEC SHEET + MEASUREMENTS

Brooks Brothers® Wrinkle-Free Stretch Pinpoint Shirt.

BB18000

Product photo



This iconic dress shirt combines a little bit of stretch with a higher back yoke for a classic fit. A premium wrinkle-free treatment process means effortless style and a sharp, professional finish all day long.

- 4.4-ounce, 97/3 cotton/spandex fine yarn count
- Taped seams
- Button-down collar
- Left chest pocket
- Pearlized buttons
- Rounded, single-button cuffs
- Rental-friendly


CARE INSTRUCTIONS

Machine Wash Warm With Like Colors. Only Non Chlorine Bleach If Needed. Tumble Dry Low. Remove Promptly And Hang. Warm Iron If Needed.

Sketches



front



back

SPEC SHEET + MEASUREMENTS

Brooks Brothers® Wrinkle-Free Stretch Pinpoint Shirt.

BB18000

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Body Length at Back	29 1/2	30	30 1/2	31	31 1/2	32	32 1/2	33
Chest	19 1/2	21	22 1/2	24	26	28	30 1/2	33 1/2
Neck Circumference	15 1/2	16	16 3/4	17 1/2	18 1/4	19	19 7/8	20 7/8
Pocket Height	4 3/4	4 3/4	5	5	5	5	5	5 1/4
Pocket Width	4 3/8	4 3/8	4 5/8	4 5/8	4 5/8	4 5/8	4 5/8	4 7/8
Sleeve Length from Center Back	33 3/4	34 1/2	35 1/4	36	36 3/4	37 1/2	38 1/4	39

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Neck Circumference: Measure from center of button to end of buttonhole along the center of the collar stand.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

SPEC SHEET + MEASUREMENTS


Brooks Brothers® Wrinkle-Free Stretch Pinpoint Shirt.

BB18000

SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL
Arm	30 1/2	32	34	35	36 1/2	37 1/2	38 1/2	39 1/2
Chest	32-34	35-37	38-40	41-43	44-47	48-51	52-56	57-61
Neck	14 1/2 - 15	15 - 15 1/2	15 1/2 - 16	16 - 16 1/2	16 1/2 - 17	17 - 17 1/2	17 1/2 - 18	18 - 18 1/2

HOW TO MEASURE



Neck Measure around the fullest part of the neck at the base. **Chest Width** Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

COLORS

Cobalt Blue

Deep Black
PMS BLACK C

Newport Blue
PMS 7681C

White