SPEC SHEET + MEASUREMENTS

Sport-Tek® Pro Perform Pullover Hoodie. ST580

Product photo



A modern performance layer with clean design lines, this double knit hoodie offers moisture wicking and snag resistance.

- 9.6-ounce, 92/8 polyester/spandex
- Moisture-wicking
- Snag-resistant
- Three-piece hood
- Self-fabric back neck tape
- Cover stitch finish on shoulders, armholes and sleeve cuffs
- Self-fabric sleeve cuffs and waistband
- Front pouch pocket

CARE INSTRUCTIONS

Machine Wash Cold With Like Colors. Only Non-Chlorine Bleach, When Needed. Do Not Use Fabric Softeners Or Dryer Sheets. Tumble Dry Low. Remove Promptly. Cool Iron, If Needed.

Sketches



front



back

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Body Length at Back	26	27	28	29	30	31	31 1/2	32
Chest	20	21 1/2	23	24 1/2	26	27 1/2	29 1/2	31 1/2
Sleeve Length from Center Back	34 1/8	34 3/4	35 3/8	36	36 5/8	37 1/4	38	38 3/4

Body Length at Back: Measured from high point shoulder to finished hem at back.


Chest: Measured across the chest one inch below armhole when laid flat.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.


SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57


HOW TO MEASURE




Neck Measure around the fullest part of the neck at the base. **Chest Width** Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.




Neck Measure around the fullest part of the neck at the base. **Chest Width** Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.



Neck Measure around the fullest part of the neck at the base. **Chest Width** Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.




Neck Measure around the fullest part of the neck at the base. **Chest Width** Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.



CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.



NECK

Neck Measure around the fullest part of the neck at the base. **Chest Width** Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

COLORS

Black	Deep Red	Iron Grey	Olive Drab Green	Silver	True Navy	True Royal	White
PMS BLACK C	PMS 201C	PMS 7540C	PMS 7771C	PMS 429C	PMS 533C	PMS 7686C	