

SPEC SHEET + MEASUREMENTS



OGIO® Fuse Polo. OG131

Product photo



Only OGIO can fuse ultramodern welding details with comfortable stretch for a sharp, distinctive look.

- 5.9-ounce, 96/4 poly/spandex pique with stay-cool wicking technology
- OGIO heat transfer label for tag-free comfort
- self-fabric collar
- OGIO stretch neck tape
- black reflective, welded left chest pocket
- set-in, open hem sleeves
- black reflective O heat transfer on left sleeve
- black reflective, welded 3-button placket with dyed-to-match, debossed O buttons
- embossed OGIO on back right shoulder
- black reflective, welded side vents

Sketches



front



back

SPEC SHEET + MEASUREMENTS



OGIO® Fuse Polo. OG131

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Body Length at Back	27 3/4	28 3/4	29 3/4	30 3/4	31 3/4	32 3/4	33 1/4	33 3/4
Chest	18	19 1/2	21	22 1/2	24	25 1/2	27 1/2	29 1/2
Pocket Height	4 1/4	4 1/4	4 1/2	4 1/2	4 1/2	4 1/2	4 1/2	4 3/4
Pocket Width	4	4	4 1/4	4 1/4	4 1/4	4 1/4	4 1/4	4 1/2
Sleeve Length	17 1/4	18	18 3/4	19 1/2	20 1/4	21	21 3/4	22 1/2

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.

Sleeve Length: Start at center of neck and measure down shoulder, down sleeve to hem.

SPEC SHEET + MEASUREMENTS




OGIO® Fuse Polo. OG131

SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57
Pocket Height	4 1/4	4 1/4	4 1/2	4 1/2	4 1/2	4 1/2	4 1/2	4 3/4
Pocket Width	4	4	4 1/4	4 1/4	4 1/4	4 1/4	4 1/4	4 1/2

HOW TO MEASURE



CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.