

WonderWink[®] WorkFlex[™] Scrub Cap WW3040

	 65/35 poly/cotton Mechanical stretch Back tie closure Covered elastic band Mender/Mick boot transfer lang at basis 	- Colored and the second se
THE REAL PROPERTY	 WonderWink heat transfer logo at back CARE INSTRUCTIONS Machine Wash Cold With Like Colors. Gentle Cycle. Use Only Non-Chlorine Bleach When Needed. Tumble Dry Low. Remove Promptly From Dryer. Cool Iron When Needed. 	front
		- august
		back
COLOR INFORMATION		
Black Ceil Blue Navy Pewter PMS PROCESS PMS 654C PMS 4320 BLACK C	Royal Teal Blue White Wine C PMS 2145C PMS WHITE PMS 222C	