

SPEC SHEET + MEASUREMENTS

CornerStone

CornerStone® Insulated Workwear Soft Shell. CSJ75

Product photo




Built with workers in mind, this insulated soft shell helps keep wind and rain out, while providing plenty of pockets for tool and gear storage.

- 100% polyester shell with water-resistant finish bonded to water-resistant film insert and a 100% polyester brushed microfleece lining
- 5.9-ounce, 100% polyfill insulation diamond quilted body
- 3.5-ounce, 100% polyfill insulation diamond quilted sleeves
- Fabric waterproof rating: 1000MM
- Fabric breathability rating: 1000G/M²
- Triple-needle stitching
- Rivet and snap details throughout
- Chest pockets with snaps, flaps and hook and loop closures
- Reinforced lower front pockets with concealed interior phone pocket
- Exposed center front zippered closure with longer pull
- Self-fabric adjustable tab cuffs with hook and loop closures
- Adjustable drawcord hem
- Decoration access pocket

Sketches



front



back

CARE INSTRUCTIONS

Machine Wash Cold. Only Non-Chlorine Bleach, When Needed. Do Not Use Fabric Softener. Tumble Dry Low. Cool Iron, If Necessary. Do Not Dry Clean.

SPEC SHEET + MEASUREMENTS



CornerStone[®] Insulated Workwear Soft Shell. CSJ75

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Body Length at Back	28 1/2	29 1/2	30 1/2	31 1/2	32 1/2	33 1/2	34	34 1/2
Chest	21	22 1/2	24	25 1/2	27	28 1/2	30 1/2	32 1/2
Sleeve Length from Center Back	35 5/8	36 1/4	36 7/8	37 1/2	38 1/8	38 3/4	39 1/2	40 1/4
Chest Pocket Height	7 1/4	7 1/2	7 3/4	7 3/4	7 3/4	7 3/4	7 3/4	8
Chest Pocket Width	5 1/2	5 3/4	6	6	6	6	6	6 1/4

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

Chest Pocket Height: Measure from top to bottom at center.

SPEC SHEET + MEASUREMENTS



CornerStone[®] Insulated Workwear Soft Shell. CSJ75

SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57

HOW TO MEASURE



CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

COLORS



Black
PMS BLACK
C



Iron Grey
PMS 7540C