


Machine wash cold with like colors. Do not bleach. Tumble dry low. Warm iron if necessary. Do not use fabric softeners.

Tips For Effectively Screen Printing Polyester Fabrics





## HOW TO MEASURE



## CHEST WIDTH

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

SIZE CHART

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57

## COLOR INFORMATION







