


Tips For Effectively Screen Printing Polyester Fabrics

Machine wash cold, gentle cycle. Do not bleach. Cool iron, if



HOW TO MEASURE



CHEST WIDTH Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

SIZE CHART XS S М L XL 2XL 3XL 4XL 38-40 44-46 Chest 32-34 35-37 47-49 50-53 5457 41-43

COLOR INFORMATION



Forest Green/







True Royal/ White White/ Black

White







needed. Do not dry clean. Wash and dry with like colors.