

SPEC SHEET + MEASUREMENTS



OGIO® Quarry Jacket. OG505

Product photo



With its dobby texture and high-performance look, this water-resistant jacket takes a stand against the elements.

- 100% poly dobby
- Zip-through cadet collar with rib knit
- OGIO heat transfer label for tag-free comfort
- Rubber OGIO detail on center back waist inner liner
- Rubber O detail at back neck
- Metalux zipper with rubber OGIO zipper pull
- Zippered right chest pocket with rubber OGIO zipper pull
- Zippered front pockets with rubber O zipper pulls and OGIO rivets
- Rib knit, self-fabric open cuffs and hem

CARE INSTRUCTIONS

Machine wash cold with like colors. Gentle cycle. Non-chlorine bleach only as needed. Tumble dry low. Use low iron. Do not dry clean.

Sketches



front



back

SPEC SHEET + MEASUREMENTS



OGIO® Quarry Jacket. OG505

PRODUCT MEASUREMENTS

| | XS | S | M | L | XL | 2XL | 3XL | 4XL |
|---------------------|--------|----|--------|--------|--------|-----|--------|--------|
| Body Length at Back | 27 1/2 | 28 | 28 1/2 | 29 | 30 | 31 | 31 1/2 | 32 |
| Chest | 19 1/2 | 21 | 22 1/2 | 24 | 25 1/2 | 27 | 29 | 31 |
| Sleeve Length | 35 1/4 | 36 | 36 3/4 | 37 1/2 | 38 1/4 | 39 | 39 3/4 | 40 1/2 |

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Sleeve Length: Start at center of neck and measure down shoulder, down sleeve to hem.

SIZE CHARTS

| | XS | S | M | L | XL | 2XL | 3XL | 4XL |
|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| Chest | 32-34 | 35-37 | 38-40 | 41-43 | 44-46 | 47-49 | 50-53 | 54-57 |

HOW TO MEASURE



CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.